

P.O.R.S.F.
11.3.31.5.1



June 20, 2001

Mr. Tom Melville
Water Quality
Department of Environmental Quality
811 SW 6th Ave
Portland, OR 97204

Re: Terminal 5 and Terminal 6 2000/20001 Dredging: Water Quality Monitoring

Mr. Melville:

Enclosed please find three letter reports:

- Reports on the Elutriate Testing and Water Quality Monitoring Programs Associated with the Terminal 5, Berth 503, and Terminal 6, Berth 603-605 Dredging Program, dated May 25, 2001;
- Field and Laboratory Analysis of Dredged Material Elutriate Quality Suttle Road Rehandle Facility, dated May 25, 2001; and
- Report of Results of the Water Quality Monitoring Programs for Terminal 5, Berth 503, and Terminal 6, Berth 603-605.

These three letter reports describe the sediment and water sampling that was performed to ensure water quality requirements were met during the 2000/2001 dredging of Terminal 5, Berth 503 and Terminal 6, Berth 603-605.

Thank you for your assistance during this project and we look forward to working with you on the next dredging project, likely to occur during the 2001/2002 dredging window.

If you have questions or comments, please do not hesitate to call me at 503/240-2011.

Sincerely,

Port of Portland
John L. Childs, P.E.
Marine Division

c: John Malek/EPA
Mark Siipola/Corps
Sebastian Degens/Port of Portland

